



Ad
DEPARTMENT OF THE NAVY
NAVAL WEAPONS SUPPORT CENTER
CRANE, INDIANA 47822-8000

N00164.AR.000055
NSWC CRANE
5090.3a

53

944

IN REPLY REFER TO:

5090/H11.9
0924

22 AUG 1990

RCRA Activities
U.S. EPA, Region V
Post Office Box A-3587
Chicago, Illinois 60690-3587

Gentlemen:

Submitted for review is the revised Interim Measures (IM) report for McComish Gorge Solid Waste Management Units (SWMU). Requirements for submittal of this report were set forth in the Corrective actions portion of the Part B Permit issued to Naval Weapons Support Center Crane (NWSCC) in January 1990.

NWSCC point of contact is Mr. Jim Hunsicker, Code 0924, telephone 812-854-3233.

Sincerely,

Encl:

- (1) Revised IM Report for the McComish Gorge SWMU
- (2) Certification Statement

Copy to:

NORTHNAVPACENCOM, Philadelphia (Code 142)
COMNAVSEASYSOM (SEA-6541)
WES

REVISED INTERIM MEASURES REPORT
FOR THE
MCCOMISH GORGE
SOLID WASTE MANAGEMENT UNIT

ENCLOSURE (1)

MCCOMISH GORGE SOLID WASTE MANAGEMENT UNIT

Purpose of Interim Measures (IM):

The requirement for submittal of the IM report was set forth in the Corrective Actions Requirements (IV. 7.) of the Part B Permit issued to Naval Weapons Support Center Crane (NWSCC) in January 1990. The purpose of the IM was to go out to the Solid Waste Management Unit (SWMU) and remove any exposed visible debris that may be accidentally removable or could cause problems for humans or animals within the area.

Location of Site:

The site is located an estimated quarter mile off of Highway 5 at the junction of Jeep Trail (JT)-1 & H-140 which is near the Crane Gate. (See attachment (1)).

Personnel doing the Inspection:

Mr. Jim Andis
Mr. Bill Litzler
Mr. Frank Coats

Finding of inspection:

The inspection of McComish Gorge site was conducted in February 1990. Personnel conducting the inspection found no visible debris at the site. A large empty wooden box was found along the south side of JT-1. JT-1 is the southern boundary of McComish Gorge.

Conditions of the Site:

The SWMU currently has grass, weeds and some small scrub brush growing on it.

Removal Procedures:

Code 0924 personnel on May 12, 1990 removed the large wooden box at the site and hauled it to NWSCC's solid fill site for disposal.

Weather Conditions:


Overcast and damp, it had rained off and on during week prior to working on Saturday.

Conclusions drawn from IM inspection:

As noted above, personnel at the time of the inspection saw no visible debris. At this time it is felt that no further action is need at the site.

Recommendations:

Routine inspection of the site every two years to insure that debris has not worked its way up to the surface.



McCOMISH GORGE

38°52'30"

INDIAN SPRINGS
3661 IV SE

55' 508 R 5 W R 4 W 509 510000m E 86°52'30"

ROAD CLASSIFICATION

- Primary highway, hard surface _____
- Secondary highway, hard surface _____
- Light-duty road, hard or improved surface _____
- Unimproved road _____
- Interstate Route
- ◻ U. S. Route
- State Route



SCOTLAND, IND.
N3852.5 — W8652.5/7.5

1979

AMS 3661 IV NW—SERIES V851


CERTIFICATION STATEMENT

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

SIGNATURE

TITLE

DATE



PWW

8/22/90