N00207.AR.002598
NAS JACKSONVILLE
5090.3a

PHOTOGRAPHIC LOG REGARDING AIR SPARGE INSTALLATION AND DRILLING
BUILDING 106 NAS JACKSONVILLE FL
4/8/1997
NAS JACKSONVILLE

ABB and Bechtel personnel in exclusion zone.
~~clean area~~

4/8/97

4/29/97 Roll 3 - Photo 12

Placement of ~~trew~~ concrete in trench leading to AIW1063

4/29/97 Roll 3 - Photo 13

Completed concrete work

4/30/97 Roll 3 - Photo 14

Well 1063 manhole cover
setup prior to concrete pour

FED OFFICE
DR 10k

Drilling activities at site. Installati-
-on of a piezometer/vapor probe

4/2/97

FED OFF
DR 10k

Installation of a piezometer/vapor probe

4/2/97

becon

Decon procedures ~~after le~~
for leang Level B area
4/2/97

POLY

Grouted boring at Building 780

4/7/97

DR 11

ABB and Bechtel personnel in exclusion zone ~~[illegible] Area~~

4/8/97

DR 10k

FED OFFICER
DEPUTY
FED OFFICER

Drilling Activities at the site. Installation of a vapor probe/piezometer.

4/2/97

5/6/97

Roll 3 - Photo 30

Excavation under the two
Concrete duct banks in the
NW - SE trench
Photo 31 does not exist

5/5/97

Roll 3 - Photo 28

View of trench leading to
AIW1066

GOVT VEHICLE

5/6/97

Roll 3 - Photo 29

Excavation under the
Concrete duct bank
in NW-SE trench

5/5/97

Roll 3- Photo 27

Area of trench opened
on 5/5/97

Photo 26 does not exist

5/14/97
Roll #4
photo #2
Bldg 10b; Pattern of trenches on the south side of the proposed Treatment pad.

5/15/97
Roll #4
photo #3

Bldg 106; Trench excavation

5/16/97

Roll # 24

photo #4

Bldg. 10 bj SVE pipe in trench

103
RENTAL

5/20/97
Roll #4
photo #5
Bldg. 10b; pressure Test
Apparatus

5/8/97 Roll 3 - Photo 38

Photograph of trench leading to treatment pad prior to concrete pour

5/8/97 Roll 3 - Photo 39

Photograph of trench leading to air sparging wells prior to concrete pour

5/8/97

Roll 3 - Photo 40

AIW1064 manhole setup prior to concrete pour

5/14/97
Roll # 4
Photo # 1

Bldg. No.: Area of Trenches

5/7/97 Roll 3 - Photo 34

Location of electric lines in the trench leading to the treatment pad.

CAT

5/7/97 Roll 3 - Photo 35

Photograph of the trench layout at the intersection of the trenches

5/7/97 Roll 3 - Photo 36

Photographs of the intersection of the trenches leading to the treatment pad and the NW-SE trench

5/7/97

Roll 3 - Photo 37

Trench leading to air sparging headers

103
103

5/21/97
Roll #4
photo 14
Bldg. 106; pouring concrete
at site

103

5/21/97
Roll #4
photo 15
Bldg. 106; concrete work
at site.

103

5/22/97
Roll #4
photo 16
Bldg. 106; cleaning up the area.

LIFTMOORE

Mis-count
No picture 17

6/9/97
Roll #4
photo 18
Bldg. 780; Level B work

PWC

5/21/97

Roll 44

photo 10

Bldg. 106; Trench prior to pour concrete

ALL-STARS

5/21/97
Roll #4
photo 14
B Ldg. lab; Trench prior to
pour concrete.

5/21/97
Roll #4
photo 12
Bldg. 106; Manhole set up
for well AIW 1068

5/21/97
Roll #4
photo 13
Bldg. 106; Manhole set up
for well 10610

5/20/97
Roll #4
photo # 6
Bldg 106; Air injection pipe in trench prior to pour concrete.

5 20 '93

5/20/97

Roll #4

photo #7

Bldg. 106; Concrete work at well AIW1068

5/20/97

Roll #4

Photo # 8
Bldg. 106; Trench prior to
pour concrete.

5/20/97

Roll #4

photo # 9

Bldg. 106; Trench prior to pour concrete.