32501.000
09.01.00.0012

5090
Code 476
8 Oct 87

N00204.AR.000054
NAS PENSACOLA
5090.3a

Mr. Charles Goddard
Northwest District Enforcement Section
Florida Department of Environmental
160 Governmental Center
Pensacola, FL 32501-5794

Re: Warning Notice #NWHW 17-1029, FLD 079170024567

Dear Mr. Goddard:

The Sampling end Analysis Plan (SAP) cited in the referenced warning Notice will he brought up-to-date and submitted to the Department.

Negotiations with the Engineering Firm (Geraghty and Hiller) which prepared the present SAP have been initiated by the Southern Division, Naval Facilities Engineering Command, Charleston, SC. We are also in the process of modifying analytical procedures, through use of a contract with Martin-Marietta (Oak Ridge National Laboratory, etc.) for work accomplished during the fiscal year. Martin-Marietta's Quality Assurance/Quality Control (QA/AC) plan is scheduled to be complete and ready by October 31, 1987. This QA/QC plan will be included as A part. of the updated SAP. The updated SAP will be submitted to you as soon thereafter as possible.

In other recommendations made in the Comprehensive Groundwater Monitoring Evaluation and Case Development Inspection, damaged wello will he repaired or replaced as required to enable us to comply with operating permit groundwater monitoring requirements. All inoperable locks will be replaced. At, present, we have no plana ta install a three foot diameter pad around each well. Each well has a pad sufficient to provide for well casing stability and to minimize potential for contamination from surface water migration down the casing. Routine sampling procedures include covering the area around the well vith clean polyethylene sheeting to protect the. cleanliness of the equipment and samples.

I remain your point of contact in this matter. If you have any questions, please contact me at (904) 452-3790.

Sincerely,

E. A. PIKE
Environmental Engineer
By direction of the Commanding Officer

Copy to:
CO SOUTHNAVFACENGCOM (1143)
CO NASP (18210)