



DEPARTMENT OF THE NAVY

CRANE DIVISION
NAVAL SURFACE WARFARE CENTER
300 HIGHWAY 361
CRANE INDIANA 47522-5001

N00164.AR.000740
NSWC CRANE
5090.3a

IN REPLY REFER TO:

5090
Ser 095/2195

10 JUN 2002

U.S. Environmental Protection Agency, Region V
Waste, Pesticides, & Toxics Division
Waste Management Branch
Corrective Action Section
Attn: Mr. Peter Ramanauskas (DW-8J)
77 West Jackson Blvd.
Chicago, IL 60604

Dear Mr. Ramanauskas:

Crane Division, Naval Surface Warfare Center (NSWC Crane) submits for review and approval the response to comments and replacement pages for the Interim Measures Report (IMR) for Rockeye (RKI). Two copies of the response to comments and replacement pages are included as enclosure (1). Enclosure (2) is the required certification statement.

NSWC Crane point of contact is Ms. Christine D. Freeman,
Code 09511, telephone 812-854-4423.

Sincerely,

James M. Hunsicker

JAMES M. HUNSICKER
Director Environmental Protection
Department
By Direction
Of The Commander

Encl:

- (1) RKI IMR Response to Comments and Replacement Pages
- (2) Certification Statement

Copy to:

Administrative Record
IDEM (D. Griffin)
SOUTHNAVFACENCOM (ES32)
TOLTEST Odon (w/o encls)

**ROCKEYE INTERIM MEASURES REPORT, REVISION 0
COMMENT RESOLUTION FOR COMMENTS SUBMITTED BY EPA
VIA CHRISTINE FREEMAN OF EPD**

Comment 1

Section 3.1.1: states that grid 7 was not sampled because of gravel. Figure C-1 states that this grid was below residential cleanup goals. How can this statement be made if the grid was not sampled? Was the gravel sampled?

Resolution 1

Section 3.1.1 is correct in its statement that grid 7 was not sampled. Figure C-1 is incorrect in showing that grid 7 met residential cleanup goals. Figure C-1 has been revised.

Comment 2

For the ICS noted in tables E-2, E-3, and E-4, provide explanation for why many constituents are no longer tested (NT notation) for after a certain time (around February 2000).

Resolution 2

As shown in Table 1-1 of the IMR, those constituents labeled with "NT" were not constituents of concern for Rockeye. Initially the laboratory erroneously analyzed for these parameters and then stopped after being informed it was unnecessary to do so. Tables E-2, E-3, and E-4 have been revised to reflect this.

Replacement Page Instructions:

- Replace binder spine insert
- Replace binder cover insert
- Replace report cover page
- Replace Figure C-1
- Replace Tables E-2, E-3, and E-4

5090
Ser 095/2195

10 JUN 2002

The letter Ser 095/2195 was for the
submittal of response to comments and
replacement pages for the Interim Measures
Report for Rockeye. The replacement pages
have been incorporated into the previously
submitted Report on 04/03/02.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

James M. Hurvick
SIGNATURE

DIRECTOR, ENVIRONMENTAL PROTECTION DEPARTMENT
BY DIRECTION OF THE COMMANDER
TITLE

6/11/02
DATE