

N00164.AR.002362  
NSA CRANE  
5090.3a

U S NAVY RESPONSES TO INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT  
COMMENTS CONCERNING DRAFT FINAL CORRECTIVE MEASURES IMPLEMENTATION  
PLAN SOLID WASTE MANAGEMENT UNIT 8 (SWMU 8) NSA CRANE IN  
10/16/2013  
NSA CRANE

**Responses to Indiana Department of Environmental Management (IDEM) Comments  
Concerning the Draft Final Corrective Measures Implementation Plan  
(Including Uniform Federal Policy Sampling and Analysis Plan)  
For Naval Support Activity (NSA) Crane, Crane, Indiana  
Solid Waste Management Unit (SWMU) 8 – Building 106 Pond**

**Note:** Responses to IDEM comments are presented in parentheses after each comment in the email from IDME to Mr. Tom Brent (below).

-----Original Message-----

From: GRIFFIN, DOUG [mailto:DGRIFFIN@idem.IN.gov]  
Sent: Wednesday, October 16, 2013 13:50  
To: Brent, Thomas CIV NAVFAC MW, PWD Crane EV  
Subject: SWMU 8 Bldg 106 Pond CMIP

IDEM accepts the change from annual sampling to biennial sampling. (**Response:** Comment noted).

I don't see the two surface water locations on any of the maps. (**Response:** Figure 17-1 has been updated to show the surface water sampling locations).

The lab methods specify 8260B and 6010C. IDEM do not require a workplan modification if the standard methods change to 8260C or 6010D, as long as the new methods meet the quantitation requirements (and as a minor correction the table on page 76 lists the metals method as SW-946 6010C). (**Response:** Comment noted. In addition, "SW-946" has been changed to "SW-846" on page 76 of the SAP).

The address for the IDEM point of contact should be:

Hazardous Waste Permit Section (there has not been a Corrective Action section for a number of years).

100 N. Senate Avenue  
MC 66-20 IGCN 1101  
Indianapolis, Indiana 46204-2251 (the PO Box was changed several years ago)

(**Response:** The address for IDEM in CMIP Section 6 has been changed to the address presented above).