

N50092.AR.000312
JEB FORT STORY, VA
5090.3a

LETTER TRANSMITTING TANK TIGHTNESS TEST RESULTS FOR TWO 10,000 GALLON
HEATING OIL TANKS BUILDING 1081 FORT STORY VA
11/10/1994
U.S. ARMY TRANSPORTATION CENTER FORT EUSTIS VA

10 NOV 1994

Directorate of Public Works

Ms. Amy Webster
Department of Environmental Quality
Tidewater Regional Office
287 Pembroke Office Park
Suite 310, Pembroke Number Two
Virginia Beach, Virginia 23462

Dear Ms. Webster:

Per your telephone conversation with Damon Doumlele on November 8, 1994, enclosed are tank tightness test results for two interconnected 10,000-gallon heating oil tanks at Building 1081, Fort Story. In February 1990 this tank system had been reported to your office as possibly leaking, as indicated by monthly soil vapor monitoring results. The enclosed test was performed in October 1990 and confirmed that the system is tight.

If you have any questions, please call Mr. Doumlele at (804) 878-4244.

Sincerely,

ORIGINAL SIGNED

Stephen A. McCall
Chief, Environmental and
Natural Resources Division

Enclosure