



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
REGION I  
JOHN F. KENNEDY FEDERAL BUILDING  
BOSTON, MASSACHUSETTS 02203-0001

N00129.AR.000586  
NSB NEW LONDON  
5090.3a

November 24, 1997

Mark Evans, Remedial Project Manager  
U.S. Department of the Navy  
Naval Facilities Engineering Command  
Northern Division  
10 Industrial Highway  
Code 1823, Mail Stop 82  
Lester, PA 19113-2090

Re: REVISED TEXT AND FIGURES FOR THE DATA GAP INVESTIGATION REPORT,  
GOSS COVE LANDFILL


Dear Mr. Evans

I am writing in response to your request for EPA to review the revised text and figures for the *Data Gap Investigation* report, Goss Cove Landfill. EPA reviewed the provided text and figures to assess whether the revisions resolve our comments dated September 19, 1997. The majority of the comments have been sufficiently addressed by the revisions with the exception of the following:

Figures 2-1, 2-2, 3-2 & 3-3      EPA requested that the bedrock surface contours be shown on at least one of the figures in the document. The bedrock contour is not shown on the revised figures provided for review.

I look forward to working with you and the CTDEP toward the cleanup of the Goss Cove site. Please do not hesitate to contact me at (617) 573-5777 should you have any questions.

Sincerely,

  
Kimberlee Keckler, Remedial Project Manager  
Federal Facilities Superfund Section

cc: Mark Lewis, CTDEP, Hartford, CT  
Andy Stackpole, NSBNL, Groton, CT  
Ken Finkelstein, NOAA, Boston, MA  
Jennifer Hayes, Gannett Fleming, Harrisburg, PA  
Corey Rich, Brown & Root, Pittsburgh, PA



Recycled/Recyclable  
Printed with Soy/Canola Ink on paper that  
contains at least 75% recycled fiber