

N00102.AR.002469  
NSY PORTSMOUTH  
5090.3a

PRESENTATION OF SLIDES AT RESTORATION ADVISORY BOARD MEETING ON 8 MAY  
2008 REGARDING FINAL REPORT FOR SHORELINE REPAIR AT OPERABLE UNIT 2 (OU 2)  
NSY PORTSMOUTH ME  
5/8/2008  
NAVFAC NORTHEAST




**Shoreline Repair at OU-2**  
**Final Report**  
**Installation Restoration Program at**  
**Portsmouth Naval Shipyard**  
*John Gildersleeve*


*08 May 2008*

*RAB*



# Installation Restoration Program




- 1 site is addressed in this presentation.
  - DRMO




# IR Sites as currently defined



# DRMO - Defense Reutilization Management Office and Site 29 Teepee Incinerator



- Filled area created with a variety of materials (1902 to 1975).
- Bulk incinerator operated on site (1965 to 1975).
- Open storage and disassembly of batteries ( 1920's to 1983).
  
- Feasibility Study




# DRMO - Defense Reutilization Management Office and Site 29 Teepee Incinerator




Late last year a loss of material was noted along the DRMO shoreline.



# DRMO - Defense Reutilization Management Office and Site 29 Teepee Incinerator



- Inspection program was instituted to monitor the area.
- Funding was secured, a contract and a schedule were put in place.
- The shoreline repair complete.




# DRMO - Defense Reutilization Management Office and Site 29 Teepee Incinerator



The total length of shore line repaired is about 110 feet.



# DRMO - Defense Reutilization Management Office and Site 29 Teepee Incinerator



The new design required the placement of 24" A-Jacks along the toe of the slope.



# DRMO - Defense Reutilization Management Office and Site 29 Teepee Incinerator



# DRMO - Defense Reutilization Management Office and Site 29 Teepee Incinerator




After the placement of the jacks the area was backfilled with stone.



# DRMO - Defense Reutilization Management Office and Site 29 Teepee Incinerator



The slope was graded and fencing replaced.




# DRMO - Defense Reutilization Management Office and Site 29 Teepee Incinerator




Public Works department at the shipyard signed off on the construction.





# QUESTIONS

A large, dark, grainy aerial photograph of the Portsmouth Naval Shipyard occupies the middle section of the page. The image shows the extensive industrial complex with numerous buildings, structures, and what appears to be a large body of water or a dry dock area in the foreground. The overall tone is very dark, with high contrast between the dark structures and the lighter sky.

PORTSMOUTH NAVAL SHIPYARD