

N83447.AR.000342
NAS FORT WORTH
5090.3a

LETTER REGARDING REGULATORY REVIEW AND NO FURTHER ACTION
RECOMMENDATION FOR SUBSURFACE HYDROCARBON CONTAMINATION AT BASE
GAS AND SERVICE STATION NAS FORT WORTH TX
9/16/1997
TEXAS NATURAL RESOURCE CONSERVATION COMMISSION



**NAVAL AIR STATION
FORT WORTH JRB
CARSWELL FIELD
TEXAS**

**ADMINISTRATIVE RECORD
COVER SHEET**

AR File Number 399

Barry R. McBee, *Chairman*
R. B. "Ralph" Marquez, *Commissioner*
John M. Baker, *Commissioner*
Dan Pearson, *Executive Director*



File: 17A-57
P.W.

399

TEXAS NATURAL RESOURCE CONSERVATION COMMISSION

Protecting Texas by Reducing and Preventing Pollution

September 16, 1997

CERTIFIED MAIL

Mr. Charles Rice
HQ AFCEE/ERB
3207 North Road
Brooks AFB, Texas 78235-5363

Re: Subsurface Hydrocarbon Contamination at the Base Gas Station (BGS) and Base Service Station (BSS), NAS Fort Worth, Carswell AFB (Tarrant County), Texas (LPST ID No. 104524 - Priority 3.2 - Facility ID No. 009696)

Dear Mr. Rice:

We have completed our review of the investigation and remedial procedures addressing subsurface contamination at the above referenced facility as provided in the final Risk-Based Assessment (RBA) and Plan B Risk Assessment reports submitted by your consultant, IT International Technology Corporation on August 17, 1997. After careful review of all available information, we are in general concurrence with your consultant's recommendation for a no further corrective action status at these sites, however, additional groundwater sampling is required to monitor Chemicals of Concern (COCs) and plume stability.

Please submit a workplan for two semi-annual groundwater sampling events according to the following plan:

Base Gas Station: Monitor wells MW-3, MW-5 and MW-6;

Base Service Station: Monitor Wells BSS-B, MW-2, MW-10 and MW-11.

Surface Water: Take an upgradient and downgradient water sample from the Fork Trinity River.

In addition, upon review of the RBA reports the following deficiency was noted. Please submit the following items:

Attachment 14: Texas Natural Resource Conservation Commission (TNRCC) Form 0019 for all wells was missing for both the BGS and BSS.

Mr. Charles Rice
Page 2

Upon completion of the above mentioned items, a report which addresses the above concerns should be submitted to this Office. Upon receipt, this project will be reevaluated and a determination made as to whether closure or further corrective action is warranted. **The LPST and Facility ID Numbers should be included in all correspondence.**

If you have any questions concerning this letter, please contact me at 512/239-2200. Your cooperation in this matter is appreciated.

Sincerely,



Antonio Peña
Coordinator, Team II
Responsible Party Remediation Section
Petroleum Storage Tank Division

ARP/keh
104524.rsk

cc: Sam Barrett, TNRCC Region 4 Field Office, 817/795-2519
(1101 East Arkansas Lane, Arlington, Texas 76010-6499)

FINAL PAGE

ADMINISTRATIVE RECORD

FINAL PAGE

FINAL PAGE

ADMINISTRATIVE RECORD

FINAL PAGE