

N00639.AR.002110
NSA MID SOUTH
5090.3a

LETTER TRANSMITTING STUDIES OF PETROLEUM CONTAMINATION AT NAVY
EXCHANGE SERVICE STATION AND REQUESTING REVIEW MILLINGTON SUPPACT TN
3/19/1992
NSA MID SOUTH

5090
Code 18236

19 MAR 1992

Mr. Francis H. Chapelle, Ph.D.
U.S. Department of the Interior
U.S. Geological Survey
720 Gracern Road, Suite 129
Stephenson Center
Columbia, S.C. 29210-7651

Subj: PETROLEUM CONTAMINATION AT NAVY EXCHANGE SERVICE STATION,
NAS MEMPHIS, MILLINGTON, TN

Dear Mr. Chapelle:

Please review the enclosed studies of the petroleum contaminated site at the Navy Exchange Service Station at NAS Memphis, TN. We want your assistance in developing the appropriate remedial technology for this site. When you are finished with your review, we need to meet to discuss your review comments.

If you have any questions, please contact Mr. John Karlyk, code 18236, at (803) 743-0624.

Sincerely,

H. J. FRASER, P. E.
MANAGER, ENVIRONMENTAL
SUPPORT SECTION

Encl:

- (1) Site Characterization Study, May 1987
- (2) Supplemental Remedial Action Plan, April 1987
- (3) Vacuum extraction Pilot Study and Remedial Investigation Report, November 1990
- (4) Quarterly Groundwater Sampling Report

Copy to:

w/o encl

NAS Memphis (Ms. Tonya Barker)
USGS Memphis (Mr. Fred Quines)

09B

182

18236

Daily

C DIR JK NAS.MEM

1823

18236x