

N00639.AR.002169
NSA MID SOUTH
5090.3a

LETTER DISCUSSING A CONTRACTING ERROR THAT RESULTED IN THE MONITORING
WELLS LOCATED AT BUILDING H-100 NOT DONE FOR THE MONTH OF JUNE
MILLINGTON SUPPACT TN
7/17/1998
MILLINGTON SUPPACT



DEPARTMENT OF THE NAVY
NAVAL SUPPORT ACTIVITY MEMPHIS
7800 3RD AVENUE
MILLINGTON, TENNESSEE 38054-5045

IN REPLY REFER TO

5090

Ser 0101 **001038**

17 JUL 1998

CERTIFIED MAIL P 615 727 211
RETURN RECEIPT REQUESTED

Mr. Ghattas Murr
TN Dept. of Environment and Conservation
Div. of Underground Storage Tanks
2510 Mt. Moriah, Suite E-645, Perimeter Park
Memphis, TN 38115-1520

Dear Mr. Murr:

Enclosure (1) is submitted for Facility ID number
0-791707.

As discussed during a telephone conversation between yourself and Mr. Randy Wilson of Naval Support Activity (NAVSUPACT) Memphis Public Works Department, Environmental Division, on July 8, 1998, due to a contracting error, the monitoring of wells located at Building H-100 was not done for the month of June 1998. This has been addressed with the contractor and will not happen again.

If additional information is required, please contact Ms. Tonya Barker or Mr. Randy Wilson of the Public Works Department, Environmental Division, at (901) 874-5462/5902.

Sincerely,

D. H. LITTON
ACTING PUBLIC WORKS OFFICER
BY DIRECTION OF THE COMMANDING OFFICER
NAVAL SUPPORT ACTIVITY MEMPHIS

Encl:

- (1) Eleventh-Period Ground Water Monitoring Report For Tanks 106 and 107 at Building H-100

5090

Ser 0101/ **001038**

17 JUL 1998

Copy to:

State of Tennessee

Dept. of Environment and Conservation

Div. of Underground Storage Tanks

4th Floor, L&C Tower, 401 Church Street

Nashville, TN 37243-1541

Commanding Officer (w/o encl)

Southern Division, Naval Facilities Engineering Command

(Code 1846)

PO Box 190010, 2155 Eagle Drive

North Charleston, SC 29419-9010