

N65928.AR.001204
NTC ORLANDO
5090.3a

LETTER REGARDING REGULATORY REVIEW AND CONCURRENCE WITH CONCLUSIONS
WITH POLYAROMATIC HYDROCARBON SOURCES AT STUDY AREA 54 NTC ORLANDO
FL
8/21/2001
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



Department of Environmental Protection

09-01-54,
0004
00644

Jeb Bush
Governor

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

David B. Struhs
Secretary

August 21, 2001

Mr. Wayne Hansel
Code 18B7
Southern Division
Naval Facilities Engineering Command
P.O. Box 190010
North Charleston, South Carolina 29419-0068

RE: Data Sheets, Compounds Detected in Soil, Study Area 54,
Naval Training Center, Orlando, Florida

Dear Mr. Hansel:

I have completed my review of the data sheets titled Compounds Detected in Soil at Study Area 54, Naval Training Center Orlando, submitted November 18, 1999 at the Orlando Partnering Team meeting.

Based upon the detections of PAHs in surface soil adjacent to the dirt road on the western portion of the site, I concur with the team's conclusion that the PAHs are most likely the result of regular vehicular traffic and are not the result of a release of contaminants. Therefore, further work to investigate contamination adjacent to this road and to conduct remediation of the PAHs is unnecessary. Continued vehicular traffic will likely impact the road in similar ways. However, if property usage of this area was to be changed from the Army Reserve's motor pool to a usage that would not be protective of human health and the environment (i.e. residential or commercial development), remediation of this area would likely be necessary.

PAHs detected on the eastern portion of the site near Family Camp Road should be further delineated.

If I can be of any further assistance with this matter, please contact me at (850)488-3693.

Sincerely,

David P. Grabka
Remedial Project Manager