



MARYLAND DEPARTMENT OF THE ENVIRONMENT
2500 Broening Highway • Baltimore Maryland 21224
(410) 631-3000 • 1-800-633-6101 • [http:// www. mde. state. md. us](http://www.mde.state.md.us)

Parris N. Glendening
Governor

Jane T. Nishida
Secretary

March 14, 2001

Shawn Jorgensen, Environmental Engineer
Indian Head Division
Naval Surface Warfare Center
ATTN: Code 046C, Bldg. D-327
101 Strauss Avenue
Indian Head, MD 20640-5035

Re: Design Quality Assurance Project Plan for Remedial Action Design at Sites 12,
41 and 42, January 2001

Dear Mr. Jorgensen:

Enclosed are comments from the Federal Facilities Section of the Maryland
Department of the Environment on the above referenced document.

If you have any questions, please contact me at (410) 631-3791.

Sincerely,

Curtis DeTore
Remedial Project Manager
Federal/NPL Superfund Division

Cc: Mr. Richard W. Collins
Mr. Karl Kalbacher
Mr. Dennis Orenshaw
Mr. Jeff Morris
Ms. Hillary Miller

**Maryland Department of the Environment
Waste Management Administration
Environmental Restoration and Redevelopment Program
Federal Facilities Section**

Comments on:

Design Quality Assurance Project Plan for Remedial Action Design at
Sites 12, 41 and 42, January 2001

Specific Comments:

1. Section 1.1, page 1-1, second paragraph
This paragraph states that the Stump Neck Annex is not on the National Priorities List (NPL). This is incorrect. Both the Main Base and the Stump Neck Annex are on the NPL as one listing.
2. Section 1.1, page 1-5, fourth complete paragraph, last sentence
Based on the imminent Toxicity Identification Evaluation (TIE) demonstration document, there may not be a need to remove any sediment from Site 42. Please reword this sentence to reflect this fact.