

9/29/05 - 04913

Singleton, Rebecca/VBO

From: Christopher CIV Jeffrey K [jeffrey.christopher@usmc.mil]
Sent: Thursday, September 29, 2005 10:48 AM
To: Jackson, Rodger W CIV NAVFAC Lant; Friedmann, William/VBO; Townsend.Gena@epamail.epa.gov; George.Lane@ncmail.net; GeorgeL100@aol.com; Bitterman, Doug/VBO
Cc: Morrison, Jeff/BOS; Tseng, Lynne/BOS
Subject: RE: OU5 FFS - Requested for Decision
Follow Up Flag: Follow up
Flag Status: Red

concur...

Jeff Christopher

Environmental Engineer
Installation Restoration Program
Environmental Affairs Department
1 CAS Cherry Point
COM: 252-466-4421
HSN: 582-4421
AX: 252-466-2000
jeffrey.christopher@usmc.mil

-----Original Message-----

From: Jackson, Rodger W CIV NAVFAC Lant [mailto:rodger.jackson@navy.mil]
Sent: Thursday, September 29, 2005 10:43
To: William.Friedmann@CH2M.com; Christopher CIV Jeffrey K; Townsend.Gena@epamail.epa.gov; George.Lane@ncmail.net; GeorgeL100@aol.com; Doug.Bitterman@CH2M.com
Cc: Jeff.Morrison@CH2M.com; Lynne.Tseng@CH2M.com
Subject: RE: OU5 FFS - Requested for Decision

I agree with the proposed changes.

Rodger W. Jackson, P.E.
NAVFAC Atlantic
Atlantic/Caribbean IPT, Code OPCEV
506 Hampton Blvd.
Norfolk, Va. 23508-1278
Tel: (757) 322-4589 Fax: (757) 322-4530
Email: rodger.jackson@navy.mil

-----Original Message-----

From: William.Friedmann@CH2M.com [mailto:William.Friedmann@CH2M.com]
Sent: Thursday, September 29, 2005 10:29
To: Jackson, Rodger W CIV NAVFAC Lant; jeffrey.christopher@usmc.mil; Townsend.Gena@epamail.epa.gov; George.Lane@ncmail.net; GeorgeL100@aol.com; Doug.Bitterman@CH2M.com
Cc: Jeff.Morrison@CH2M.com; Lynne.Tseng@CH2M.com
Subject: OU5 FFS - Requested for Decision
Importance: High

Team,
As a result of additional sampling conducted at OU5 after the completion of the 2002 RI sampling effort, two changes are proposed for the Final OU5 FFS.

11/18/2006

In the draft FFS, two wells at Site 2 of OU5 are described as having benzene exceedances of the NC 2L standard. In Well 2MW01, benzene was present at 1 ug/L, the same level as the standard. In four subsequent sampling events (2003, two in 2004, and one in 2005), benzene was detected in only 2003 and at a concentration below the standard (see table below). In accordance with the described preferred alternative, these four consecutive sampling rounds with concentrations less than the NC 2L would result in this well being dropped from the sampling list. We would like to mention these sampling rounds in the Final FFS so that we are left with only one well to be monitored.

OU5-2MW01	Benzene Concentration (ug/L)
2002 RI	1
11/18/03	0.5 U
11/18/03	0.14 J
05/18/04	0.5 U
12/07/04	0.5 U
05/24/05	0.5 U

(duplicate sample)

Secondly, in the remaining well (S2-TW03), two additional constituents were detected above the NC 2L standards in subsequent VGM sampling events following the RI. TCE was detected at 7.1 and 10 ug/L, and vinyl chloride was detected at 0.4 J ug/L and 0.48 J ug/L, respectively. Each of these detections is above the standards of 2.8 ug/L for TCE and 0.015 ug/L for vinyl chloride. We intend to describe these sampling results in the FFS and call out these two additional constituents as COCs to be monitored for as part of the preferred alternative. It is also worth noting that S2-TW03 is a temporary well which be converted to a permanent well.

OU5-S2-TW03	Benzene (ug/L)	TCE (ug/L)	Vinyl Chloride (ug/L)
NC 2L STANDARD	1	2.8	0.015
2002 RI	2	NA	1 U
2002 RI	2	NA	1 U
11/18/03	2.1	7.1	0.4 J
05/20/04	3	10	0.48 J
12/7/04	0.82	2.3	0.5 U

(duplicate sample)

Please let me know if you have comfortable with these changes to the Final FFS. Also let me know if you need any additional information or would like to see a copy of the full data tables for the past few years of monitoring.

Thanks,
Bill



CH2MHILL

William J. Friedmann, Jr. P.G.
Project Manager/Hydrogeologist
CH2M HILL, Inc.
5700 Cleveland Street, Suite 101
Virginia Beach, VA 23462
Ph: 757-671-8311 x419
Fx: 757-497-6885E-mail: william.friedmann@ch2m.com