



**UNITED STATES ENVIRONMENTAL PROTECTION AGENCY**  
**REGION 5**  
**77 WEST JACKSON BOULEVARD**  
**CHICAGO, IL 60604-3590**

**Memorandum**

**March 5, 1999**

**From: Carol Witt-Smith**  
**U.S. EPA Region 5, WPTD, WMB**

*Carol Witt-Smith*

REPLY TO THE ATTENTION OF:

**To: Tom Brent**  
**U.S. Navy, NSWC, EPD**

**Tom- I went over the recommendations for parameters for the landfarm with Al Debus. We agree with the following list of parameters, with the addition that we discussed regarding sulfides. If you have any questions regarding this matter, please contact me or Al.**

**Landfarm QAP Parameter List**

**Appendix IX Metals (SW-846 Method 6020 ICP/MS)**

**Miscellaneous Parameters (Table 1-2, Page 2 of 9)**

**Appendix IX Volatile Organic Compounds (SW-846 Method 8260B w/25ml Purge)**

**Explosives (SW-846 Method 8330)**

**If sulfides are tested for add: Ground Water pH and Dissolved Oxygen**

**cc: Al Debus, WMB**  
**Bill Gates, SOUTHDIV**