

N00213.AR.000439
NAS KEY WEST
5090.3a

LETTER REGARDING FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION
REVIEW OF GROUNDWATER MONITORING REPORT FOR BOCA CHICA FLYING CLUB
SITE NAS KEY WEST FL
2/23/2000
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



Department of Environmental Protection

Jeb Bush
Governor

Twin Towers Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

David B. Struhs
Secretary

February 23, 2000

Mr. Byas Glover, Code 5651
SOUTHDIIV
Post Office Box 190010
North Charleston, SC 29419-9010


RE: Groundwater Monitoring Report for Flying Club Site. Key
West, Florida

Dear Mr. Glover:

I have reviewed the above referenced document dated February 2000 (received February 14, 2000). The recommendations stated on page 3 of the report are adequate. Please note that the results of the Interim Remedial Action (Ion Collider Method) for this site have yet to be submitted to this office. I would appreciate if said records are submitted before our next scheduled team meeting.

If I can be of any assistance in this matter, please contact me at 904/488-3935.

Sincerely,



Jorge R. Caspary, P.G.

Q A Record

cc: Rick Ofsanko, TTNUS-Deerfield Beach
Ron Demes, NAS Key West

TJB B

JJC JJC

ESN ESN

Kw52000.doc