

N65928.AR.001616
NTC ORLANDO
5090.3a

LETTER REGARDING REGULATORY REVIEW AND RECOMMENDATIONS ON DRAFT
INVESTIGATION OF HAWTHORN FORMATION AND VADOSE SOIL AT OPERABLE UNIT 4
(OU 4) NTC ORLANDO FL
1/26/2009
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION



Florida Department of Environmental Protection

Bob Martinez Center
2600 Blainstone Road
Tallahassee, Florida 32399-2400

Charlie Crist
Governor

Jeff Kottkamp
Lt. Governor

Michael W. Sole
Secretary

January 26, 2009

BRAC PMO SE
Attn: Mr. Art Sanford
4130 Faber Place Drive
Suite 202
North Charleston, SC 29405

RE: Draft Investigation of the Hawthorn Formation and Vadose Soil for Operable Unit 4, Naval Training Center Orlando, Orlando, Florida.

Dear Mr. Sanford:

I have completed my review of the Draft Investigation of the Hawthorn Formation and Vadose Soil for Operable Unit 4, Naval Training Center Orlando, dated September 2008 (received September 9, 2008), prepared and submitted by Tetra Tech NUS, Inc. The report adequately describes the results of the investigation to this point. The recommendations in the report are for further evaluation of vadose zone contamination leaching to groundwater, the monitoring and removal of DNAPL and the continued investigation of the Hawthorn water bearing zone to the north of the site. These recommendations are acceptable to the Department. However, the recommendation to sample all channels of CMT wells 68D, 69D and 70D is too limited. Since most of the data presented in the report is dated (2006), a complete round of groundwater sampling of all Hawthorn zone wells and all channels of CMT wells should be conducted.

If you have any concerns regarding this letter, please contact me at (850) 245-8997.

Sincerely,

David P. Grabka, P.G.
Remedial Project Manager

CC: Greg Fraley, EPA Region 4
Sam Naik, CH2M Hill, Atlanta
~~Teresa Grayson, Tetra Tech NUS, Oak Ridge~~

JJC *for* ESN *for*