N00639.AR.002106
NSA MID SOUTH
5090.3a

VARIOUS PHOTOS FROM CLEANUP EFFORTS AT BUILDING 121 MILLINGTON SUPPACT TN
2/1/1997
U S NAVY

D1,26

N-121 - Red Soil next to sidewalk where the vat turned over; 8 Apr 97, (Composite sample)

N-121 8 Apr 97
Acid spill, prior to remediation
(Burned soil)

Concrete spots with sand filler between them, inside N-121
Feb 97

N-121 Looking East Feb 97

N121 Cleanup 8 Apr 97

N-121 Looking east Feb 97

N-121 Cleanup 8 Apr 97

N-121- Awaiting sample results
After removal of soil. 8 Apr-97 RJM

Mark Thomas, TDEC taking grab sample
at N-121, 0930, on 8 Apr97.
L to R: Alan Parks (TDEC), Kevin Chazak (En Safe), Jim
Heide, Bill Bradshaw (En Safe).