

N00639.AR.002183
NSA MID SOUTH
5090.3a

TRANSMITTAL LETTER WELL ABANDONMENT AT NAVY FLYING CLUB FACILITY ID 0-
790479 MILLINGTON SUPPACT TN
3/31/1999
MILLINGTON SUPPACT



DEPARTMENT OF THE NAVY
NAVAL SUPPORT ACTIVITY MID-SOUTH
5720 INTEGRITY DRIVE
MILLINGTON, TENNESSEE 38054-5045

IN REPLY REFER TO

5090
Ser 0101/000403
31 MAR 1999

CERTIFIED MAIL Z 227 158 448
RETURN RECEIPT REQUESTED

Mr. Ghattas Murr
TN Dept. of Environment and Conservation
Division of Underground Storage Tanks
2510 Mt. Moriah, Perimeter Park, Suite E-645
Memphis, TN 38115-1520

Dear Mr. Murr:

Per your letter of March 1, 1999, enclosure (1) is submitted for the well abandonment at the Navy Flying Club, Facility ID# 0-790479.

If any additional information is required, please contact Ms. Tonya Barker or Mr. Randy Wilson of the Public Works Department, Environmental Division, at (901) 874-5462/5902.

Sincerely,

DONALD H. LITTON
Acting Public Works Officer
By direction of the Commanding Officer
Naval Support Activity Mid-South

Encl:

(1) EnSafe Inc. ltr of March 19, 1999 (Well Abandonment at the Navy Flying Club (Facility ID#0-790479))

Copy to:

State of Tennessee
Dept. of Environment and Conservation
Div. of Underground Storage Tanks
Fourth Floor, L&C Tower, 401 Church Street
Nashville, TN 37243-1541

Commanding Officer
(Code 1846)
SOUTHNAVFACENCOM
P.O. Box 190010
North Charleston, SC 29419-9010



ENSAFE INC.

ENVIRONMENTAL AND MANAGEMENT CONSULTANTS

5724 Summer Trees Drive • Memphis, Tennessee 38134 • Telephone 901-372-7962 • Facsimile 901-372-2454 • www.ensafe.com

March 19, 1999

Commanding Officer
Att: Mr. Randy Wilson
Public Work Office, Environmental Division
Naval Support Activity Mid-South
Millington, Tennessee 38054-5000

Re: Well Abandonment at the Navy Flying Club (Facility #0-790479)
Naval Support Activity Mid-South; Millington, Tennessee

Dear Randy,

As requested by the Navy, EnSafe abandoned the six monitoring wells (FCMW-1, FCMW-2, FCMW-3, FCMW-4, FCMW-5 and FCMW-6) at the Navy Flying Club on March 11, 1999. Monitoring wells were abandoned in accordance with Rules and Regulations of Wells in Shelby County (Section 9) by our subcontractor Tri-State Testing, a certified licensed well driller in Tennessee (License # 198542). Wells were initially chlorinated with liquid bleach followed with grouting by lowering a tremie pipe to the bottom of the well and pumping a grout mixture of Portland cement/bentonite until the grout reached the surface. Surface completions were removed and patched over with concrete. EnSafe personnel were onsite at all times during the well abandonment procedures.

An emergency permit for closing the wells was secured from the Memphis Shelby County Health Department (MSCHD) Division of Pollution Control by the drilling subcontractor (Permit No. 990690828) before the wells were abandoned. The application for closing the wells has been filed with the MSCHD, which will issue you a hard copy of the permit after they process it (generally takes 30 to 60 days).

This should conclude the activities associated with Delivery Order #002 under contract N62467-98-D-0937. It has been a pleasure working with you and John on this project. As always, please feel free to call me with any questions.

Sincerely,

EnSafe, Inc.

Jeff Bennett
Sr. Project Manager

cc: John Karlyk
File D.O. 002