

N60478.AR.001416  
NWS EARLE  
5090.3a

LETTER DISCUSSING DISCHARGE FROM UNDERGROUND TANK SYSTEM NWS EARLE  
NJ  
7/14/1994  
STATE OF NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION



State of New Jersey  
DEPARTMENT OF ENVIRONMENTAL  
PROTECTION AND ENERGY

JUL 14 1994

CHRISTINE TODD WHITMAN  
Governor

ROBERT C. SHINN, JR.  
Commissioner

John Pawlus  
Navel Weapons Station Earle  
201 South Route 34  
Colts Neck, NJ 07722

Re: Discharge from Underground Storage Tank System  
Navel Weapons Station Earle, 201 South Route 34  
Colts Neck, Monmouth County, Case #93-11-17-0856-11  
UST #0151003

Dear Mr. Pawlus:


On November 17, 1993, the New Jersey Department of Environmental Protection and Energy (Department) received notification of a suspected diesel fuel and #2 heating oil discharge caused by an underground storage tank systems (USTs) at the above referenced facility which are regulated pursuant to the Underground Storage of Hazardous Substances Act, N.J.S.A. 58:10A-21 et seq. (NJUSHSA). Therefore the owner or operator of the above referenced facility shall comply with the reporting requirements in accordance with NJUSHSA and the regulations promulgated thereto, N.J.A.C. 7:14B.

In accordance with N.J.A.C. 7:14B-8.3(a), a written report was due to be submitted to the Bureau of Field Operations (BFO) on or before March 17, 1994. As of this time, the Department has not received the required report. The Department is prepared to stay any enforcement action at this time for this late submittal provided a written Remedial Investigation (RI) Report is submitted within 60 days upon receipt of this letter. To facilitate processing, please reference the case number (discharge notification number), the Closure Approval number (if applicable) and the UST registration number in the report.

Please review the enclosed UST Discharge Response guidance document prior to submitting any information to the NJDEPE. The guidance document briefly describes the UST Discharge Response procedures.

If you should have any technical questions pertaining to the remediation of the above referenced facility, please call the Site Remediation's General Question telephone line at (609) 633 - 7141. Should you have any other questions concerning this correspondence, please contact Janice DiClaudio, Case Manager, at the following address and telephone number: New Jersey Department of Environmental Protection and Energy, Division of Responsible Party Site Remediation, CN 028, Trenton, NJ 08265-0028, (609) 633 - 7141.

Respectfully,

  
Carlton Dudley, Supervisor  
Bureau of Field Operations

Enclosures: UST Discharge Response guidance document  
Laboratory Deliverables Checklist  
Management of Excavated Soils



C: Janice DiClaudio, BFO  
Health Department

