

N60478.AR.001679
NWS EARLE
5090.3a

LETTER TRANSMITTING DRAFT FINAL REPORT REMEDIAL INVESTIGATION
UNDERGROUND STORAGE TANKS FOR GROUP II SITES AND CLARIFICATION TO U S
NAVY COMMENTS NWS EARLE NJ
1/25/1996
BROWN AND ROOT ENVIRONMENTAL



Brown & Root Environmental

993 Old Eagle School Road, Suite 415
Wayne, PA 19087-1710

(610) 971-0900
FAX: (610) 971-9715

C-51-1-6-40

January 25, 1996

Project Number 5333

Mr. Brian Helland, Code 1812
Senior Environmental Engineer
Northern Division
Naval Facilities Engineering Command
10 Industrial Highway Mailstop 82
Lester, Pennsylvania

Reference: Contract No. N62472-90-D-1298 (CLEAN)
Contract Task Order No. 226

Subject: Submission of Final Report
UST RI Report for Group II Sites
NWS Earle - Colts Neck, New Jersey

Dear Mr. Helland:

Brown and Root (B & R) Environmental Corporation is pleased to provide four copies of the subject report. We are providing you with two copies and we forwarded two copies to Greg Goeperft at NWS Earle.

We have revised the report in accordance with the Navy's December 18, 1995 Memorandum. Please consider the following in relation to the noted comments:

Page 2-12, Section 2.3.1

We reviewed correspondence from the Navy to the New Jersey Department of Environmental Protection (NJDEP) contained in the appendices of the RI work plan. The correspondence indicates that the 93-6-11-0756-05 incident discharge number applies to the removal of UST C8/1. To avoid confusion, we deleted the sentences in the RI report that pertained to UST C8/2. This is appropriate since no RI activities were required at C8/2. We also deleted the sentence that discussed the tightness test; this information is not necessarily relevant.

Page 2-32, Section 5.1

We reviewed the UST closure report for R4B/1 contained in the appendices to the RI work plan. This report indicates that the closure activities occurred on August 11, 1994. This same report also indicates that the Navy reported an apparent release, observed during the closure activities, to the NJDEP Hotline; it was assigned the Spill Case No. 94-9-22-1032-56. We have revised the RI report to more clearly indicate this information.



BRPH51-1-6-40
Mr. Brian Helland, Code 1812
Naval Facilities Engineering Command
January 25, 1996 - Page 2

As always, we appreciate the opportunity to complete technical services for the Navy. Do not hesitate to contact me if you have questions or require revisions to the subject report.

Sincerely,

Richard J. Gorrell
Project Manager

c: Greg Goepfert, Navy (NWS Earle)
John Trepanowski, P.E. (B & R Environmental)
Michael Turco, D.E.E., P.E. (B & R Environmental)
Russell Turner (B & R Environmental)

INSTRUCTIONS FOR REPORT ASSEMBLY

1. REMOVE HAND STAMPED "DRAFT" HARD COPY REPORT COVER FROM PLASTIC FRONT POCKET COVER OF 3-RING BINDER AND REPLACE WITH FINAL HARD COPY REPORT COVER.
2. INSERT FINAL HARD COPY "BINDER SPINE" TITLE INTO PLASTIC POCKET ON SIDE OF 3-RING BINDER.
3. OPEN 3-RING BINDER AND REMOVE ALL DRAFT PAGES UP TO, BUT NOT INCLUDING THE APPENDIX A DIVIDER PAGE. DISCARD THESE PAGES AND REPLACE WITH FINAL REPORT SECTIONS. NOTE THAT THE FINAL REPORT SECTIONS INCLUDE PRE-PLACED DIVIDER PAGES FOR THE TABLE OF CONTENTS, EXECUTIVE SUMMARY, AND SECTIONS 1 AND 2.
4. ALL APPENDICES THAT WERE ORIGINALLY INCLUDED WITH THE "DRAFT" REPORT REMAIN THE SAME IN THE FINAL REPORT.
5. INSERT TABLE C-1 INTO APPENDIX C DIRECTLY FOLLOWING THE APPENDIX DIVIDER PAGE.
6. EXTRA COPIES OF THE DRAFT REPORT MAY BE RETURNED TO BROWN AND ROOT ENVIRONMENTAL.