N00207.AR.002564
NAS JACKSONVILLE
5090.3a

PHOTOGRAPHIC LOG REGARDING DRMO PROJECT AT POTENTIAL SOURCE OF CONTAMINATION 45 (PSC45) NAS JACKSONVILLE FL

4/22/1994

NAS JACKSONVILLE

TITLE: PSC 45DRMO

DATE(S): 4/22/1994

PSC-46
Looking toward 2 from west

PSC 46

#4 Looking North

PSC-46

#5 Looking South

PSC-46
#6 Looking South

SOI

PSC46-DRMO

PSC - 46

Looking toward #3

from east

PSC 46 - DRMO

PSC46 - DRMO

PSC 46 - DRMO

PSC 46

#9 Looking North

PSC-46
#7 Looking North

SOI

PSC 46

#8 Looking South

PSC46 - DRMO

#1 Looking West

PSC-46

PSC 46 - DR MO

PSC 46 - DRMO

NAS JAX RDS

4/22/94

PSC 46: View of o/w separator and ditch at SE corner of facility.

NAS JAX RDS

4/22/94

PSC 46: W side looking S. Unpaved (stained soil?)

NAS JAX RDS

4/22/94

PSC 46: Transformers stored along W side

CORROSIV

NAS JAX RDS

4/22/94

PSC 46: Batteries stored along W side.

PSC 46 - DRMO

PSC 46 - DRMO

PSC 46 - DRMO

PSC-46

#5 Looking slightly North