N00207.AR.002568
NAS JACKSONVILLE
5090.3a

# PHOTOGRAPHIC LOG REGARDING POTENTIAL SOURCE OF CONTAMINATION 9 (PSC9)
NAS JACKSONVILLE FL
3/1/1999
NAS JACKSONVILLE

**TITLE:** PSC 9

**DATE(S):** 3/1999

P-1 (roll 1) 11-11-97

One excavation for RAD-contaminated soil
soil at PSC9

P-2 (roll 1) 11-11-97

An area excavated at PSC9 for rad-contaminated soil

Note: Drum

PSC 9
Near location 09W00301,
looking east

location 095Bk101, upgradient background location

~~09SBk~~ near
PSC 9, location 09W00301
ditch system looking east

near location 095BK101,
looking east

PSC 9, looking at N. Richard-
son
standing near
location 09500102

at PSC9, near location
09W00301, close up of
plant growing in styrofoam
vessel

PSC 9, near location
09W00301 looking
at small ditch system

near location 09W00301
looking east, RSC 9

PSC 9, near location
095 00102 looking east

psc 9, standing near
lectern 09W00201

standing at PSC 9 location
09 S00102 looking west
towards N. Richardson.

PSC 9, standing near
location of W00201,
road in upper right corner
is part of Catapult Rd.

near background location
095BK101, looking west.

near PSC 9, location 095BK101 as background sample. (A.Ohs)

NAS JAX RDS

4/21/94

PSC 9: View to N at E end.

NAS JAX RDS

4/21/94

PSC 9: View to E

PSC 9

MW 001

11-17-97

p-12

Collection of soil sample from base of rad-excavation area at PSC9